




## **Operating Instructions**


# Sartorius Extend Series Sartorius Gem and Gold Extend

Electronic Analytical and Precision Balances and Precious Metal Scales











## **Contents**

- 4 Warnings and Safety Precautions
- **5 Getting Started**
- 6 Installation
- 10 Leveling the Balance/Scale
- 11 Below-Balance/Scale Weighing
- 12 **Operation**
- 12 Display and Operating Elements
- 13 Basic Weighing Function
- 14 Calibration/Adjustment
- 17 Configuration (Operating Menu)
- 17 Functions of the Keys during Configuration
- 18 Menu Navigation; Example: Setting the Language
- 19 Parameter Settings: Menu
- 20 Parameter Settings: Overview
- 26 Application Programs
- 26 Counting
- 28 Weighing in Percent
- 30 Calculation
- 32 Animal Weighing/Averaging
- 34 Net-total Formulation
- 36 Totalizing
- 38 Mass Unit Conversion
- 40 Density Determination

- 41 ISO/GLP-compliant Printout/Record
- 43 Interface Port
- 49 Pin Assignment Chart
- 50 Cabling Diagram
- 51 Troubleshooting Guide
- 52 Care and Maintenance
- 53 Recycling
- 54 Overview
- 54 Specifications
- 57 Accessories
- 59 Declaration of Conformity

## **Warnings and Safety Precautions**

#### Safety

To prevent damage to the equipment, please read these operating instructions carefully before using the balance/scale.



\ Do not use this equipment in hazardous areas.



The balance/scale may be opened only by trained service technicians.



/!\ Disconnect the balance/scale from power before connecting or disconnecting peripheral devices.



/!\ If you operate the balance/scale under ambient conditions subject to higher safety standards, you must comply with the applicable installation regulations.



\ Exposure to excessive electromagnetic interference can cause the readout value to change. Once the disturbance has ceased, the instrument can be used again in accordance with its intended purpose.

Make sure that no liquid enters the equipment housing; use only a slightly moistened cloth to clean the balance/scale.



#### Installation

Make sure the voltage rating printed on the power supply is identical to your local line voltage.

Proceed with extreme caution when using pre-wired RS-232 connecting cables, as the pin assignments may not be compatible with Sartorius equipment. Before connecting the cable, check all pin assignments against the cabling diagrams and disconnect any lines that are assigned differently.



/!\ If there is visible damage to the equipment or power cord, disconnect the equipment from power and lock it in a secure place to ensure that it cannot be used for the time being.

- Connect only Sartorius accessories and options, as these are optimally designed for use with your Extend balance/scale. The operator shall be solely responsible for installation and testing of any modifications to Sartorius equipment. including connection of cables or equipment not supplied by Sartorius. On request, Sartorius will be happy to provide information on operating specifications (in accordance with the Standards for defined immunity to interference).
- $\bigcirc$ Do not open the balance/scale housing. If the seal is broken, this will result in forfeiture of all claims under the manufacturer's warranty.
- $\bigcirc$ If you have any problems with your balance/scale, contact your local Sartorius customer service center.

#### Symbols

The following symbols are used in these instructions:

- indicates required steps
- indicates steps required only under certain conditions
- > describes what happens after you have performed a particular step
- indicates an item in a list



indicates a hazard

## **Getting Started**

#### **Storage and Shipping Conditions**

 Do not expose the balance/scale to extreme temperatures, moisture, shocks, blows or vibration.

#### **Unpacking the Equipment**

- After unpacking the equipment, please check it immediately for any external damage.
- If you detect any damage, proceed as directed in the chapter entitled "Care and Maintenance," under "Safety Inspection."
- Save the box and all parts of the packaging for any future transport.
   Disconnect all cables before packing the balance/scale for shipping.

#### **Equipment Supplied**

- Balance/scale
- Weighing pan
- Pan support (only for models with a round weighing pan)
- Gem tray (GK and GW models only)
- AC adapter

Additional equipment supplied with models ED224S, ED124S, GK1203, GK703, GK303:

- Sliding-door draft shield
- Shield ring
- Shield plate
- Dust cover

Additional equipment supplied with models ED423S-DS, ED323S-DS, ED153-DS, GK2202:

- Sliding-door draft shield

Additional equipment supplied with models ED623S(-CW), ED523S-POCE, ED423S(-CW), ED323S(-CW), ED153(-CW):

- Round glass draft shield with cover

#### Installation

Choose a location that is not subject to the following negative influences:

- Heat (heater or direct sunlight)
- Drafts from open windows and doors
- Excessive vibration during weighing
- Excessive moisture

#### Conditioning the Balance/Scale


Moisture in the air can condense on cold surfaces whenever the equipment is moved to a substantially warmer place. To avoid the effects of condensation, condition the weighing instrument for 2 hours at room temperature, leaving it unplugged from AC power.

Seal on Balances/Scales Verified for Use in Legal Metrology in the EU\*:

EU legislation requires that a control seal be affixed to verified balances/scales of accuracy class ①. The control seal consists of a sticker with the "Sartorius" logo. If the seal is broken, the verification becomes null and void and the balance/scale must be re-verified.

\* Including the Signatories of the Agreement on the European Economic Area


### Installation



#### Setting Up the Balance/Scale


Instruments with sliding-door draft shield:

- Place components inside the chamber in the following order:
- Shield plate
- Shield ring (not on models ED423S-DS, ED323S-DS, ED153-DS, GK2202)
- Pan support
- Weighing pan
- Gem tray (GK models only)



Instruments with a round glass draft shield:

- Position the components listed below in the order given:
- Place the lower lid on the balance/scale with the raised edge facing upwards and turn it until it is firmly in position
- Pan support
- Weighing pan
- Glass draft shield
- Gem tray (GK models only)
- Place the upper lid on the draft shield with the raised edge facing downwards





Instruments with a round weighing pan

- Position the components listed below in the order given:
- Pan support
- Weighing pan
- Weighing bowl (GW models only)

Instruments with a rectangular weighing pan:


- Place the weighing pan on the balance/scale
- Weighing bowl (GW models only)





Use only genuine Sartorius AC adapters. For use within Europe: part no. 6971948

- Connect the angle plug to the balance/scale
- Connect the AC adapter to the wall outlet (mains)



AC Adapter with Country-specific Power Cord Some models come with separate country-specific power cords for the AC adapter. In Europe, use only genuine Sartorius AC adapter part no. 6971982.

- Connect the angle plug to the balance/scale
- Select the power cord for your area and connect it to the AC adapter
- Plug the power cord into the wall outlet (mains)

The ground terminal is connected to the balance/scale housing, which can be additionally grounded for operation.



#### Set the required voltage, if necessary.

If you need to set the voltage, use one of the following genuine Sartorius adapters:

- TNG8 adapter, part no. 6971951 (universal)
- TNG8 adapter, part no. 6971952 (for the UK)
- Move the switch to set the voltage to 230 V or 115 V

NOTE: This equipment has been tested and found to comply with the limits pursuant to part 15 of FCC Rules.

These limits are designed to provide reasonable protection against harmful interference. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with these instructions, may cause harmful interference to radio communications.

For information on the specific limits and class of this equipment, please refer to the Declaration of Conformity. Depending on the particular class, you are either required or requested to correct the interference.

If you have a Class A digital device, you need to comply with the FCC statement as follows: "Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense."

If you have a Class B digital device, please read and follow the FCC information given below:
"However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:


- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help."

Before you operate this equipment, check which FCC class (Class A or Class B) it has according to the Declaration of Conformity included. Be sure to observe the information of this Declaration



#### **Connecting Electronic Peripheral Devices**

 Make sure to unplug the balance/scale from AC power before you connect or disconnect a peripheral device (printer or computer) to or from the interface port.




#### **Warmup Time**

To ensure accurate results, the balance/scale must warm up for 30 minutes before operation. Only after this time will the instrument have reached the required operating temperature.

Using Verified Balances/Scales in Legal Metrology in the EU\*:

 Make sure to allow the equipment to warm up for at least 24 hours after initial connection to AC power or after a relatively long power outage.

\* Including the Signatories of the Agreement on the European Economic Area




#### Leveling the Balance/Scale

#### Purpose:

To compensate for unevenness at the place of installation


Always level the balance/scale again any time after it has been moved to a different location. Only the 2 front feet are adjusted to level the balance/scale.


- Retract the two rear feet (only on models with a rectangular weighing pan).
- Turn the 2 front feet as shown in the diagram until the air bubble is centered within the circle of the level indicator.
- > In most cases this will require several adjustment steps.
- On models with a rectangular weighing pan: extend the 2 rear feet until they touch the surface on which the balance/scale rests.



#### Anti-theft Locking Device


• To secure the balance/scale at the place of installation, fasten a chain or a lock to the lug located on the rear panel of the balance/scale.





A port for a below-balance/scale weighing hanger is located on the bottom of the balance/scale.


- Below-balance/scale weighing is not permitted in legal metrology.
- Open cover plate on the bottom of the balance/scale.
   Important: set the balance/scale on its side to access the cover plate. DO NOT turn the balance/scale upside-down!



- Using the built-in hook 1: Attach the sample (e.g., using a suspension wire) to the hanger.
- Bore hole 2 (not on models ED153.., ED822.., ED8201, ED5201, or ED2201): Carefully fasten the special hanger, or order a hanger directly from Sartorius.
- Install a shield for protection against drafts if necessary.

## **Operation**

### **Overview of Display and Operating Elements**



Position	Designation
1	Weight units
2	Menu level indicator
3	Taring
4	Symbol:
	"GLP printing mode active"
5	Symbol: "Printing mode active"
6	Symbol:
	"Application program active"
7	Data output:
	Press this key to send readout
	values to the built-in data
	interface.
8	Calculated-value indicator
	(i.e., not a weight value)
9	Start an application program
10	Symbol: Gross or net value
11	Select an application program
	Open the operating menu
12	Symbols for active application
	(Δ¯Δ, <b>ஃ</b> , %, 😂, <b>土</b> , A, C)

Position	Designation
13	Delete (Clear Function)
	This key is generally used to
	cancel functions:
	<ul> <li>Quit application program</li> </ul>
	<ul> <li>Cancel calibration/adjustment</li> </ul>
	routine   Exit the operating menu
14	Start calibration/adjustment routine
15	On/off
16	Symbol:
	Calibration/adjustment function
17	Symbols for zero range
	(verified models only)
18	Level indicator
19	Weight value displayed
	in selected weight unit
Symbols	:
<<	Save settings and exit the
	operating menu
<	One menu level higher
V	Scroll through menu items
>	Next item on current menu level
1	Select a parameter setting

## **Basic Weighing Function**

#### **Features**

- Taring the balance/scale
- Printing weights

#### Preparation

- Switch on the balance/scale: Press (1/0)
- Tare the balance/scale, if necessary: Press (Tare)
- If necessary, change the configuration see the chapter entitled "Configuration"
- O If desired, load the factory settings: see the chapter entitled "Configuration"

**Additional Functions** 

O Switching off the balance/scale: Press (1/b)

#### Example Simple Weighing

	Step	Key (or instruction)	Displ	ay/Printou	ıt	
1.	Switch on the balance/scale Self-test is performed, followed by automatic initial tare function.	(I/O)		0.0 g		
2.	Place container on weighing pan (in this example: 11.5 g).	<u></u>	+	1 1.5 g		
3.	Tare the balance/scale	Tare		0.0 g		
4.	Place sample in container (in this example: 132 g).		+	132.0 g		
5.	Print weight.		N	+	132.0 g	

## **Calibration and Adjustment**

#### **Purpose**

Calibration is the determination of any difference between the measured value displayed and the true weight (mass) of a sample. Adjustment is the correction of this difference, or its reduction to an allowable level within maximum permissible error limits.

Using Verified Balances/Scales as Legal Measuring Instruments in the EU\*: Before using your balance/scale as a legal measuring instrument, internal calibration must be performed at the place of installation.

#### **Features**

Calibration/adjustment can be performed only when:

- there is no load on the balance/scale,
- the balance/scale is tared, and
- the internal signal is stable.

If these conditions are not met, an error message is displayed ("ERR 02").


The weight displayed for the sample on the balance/scale must not differ from the nominal weight by more than 2%. You can use any of the following weight units in calibration/adjustment: EAL.UNII: GRAMS, KILDGR, or POUNIS

## External Calibration in Verified Balances/Scales of Accuracy Class

- When the balance/scale is used in legal metrology, external calibration is blocked by a seal over the menu access switch.
- \* Including the Signatories of the Agreement on the European Economic Area

To block calibration/adjustment:

- Select EAL.-ADJ.: BLOCKED in the menu and
- Close the menu access switch on the back of the balance/scale



For details on generating an ISO/GLP-compliant printout of calibration/adjustment results, see page 41.

Following calibration/adjustment, the application program is cleared.

#### Internal Calibration/Adjustment

In the operating menu, select <code>CAL.-Ald.:</code> <code>CAL.INT.</code> before beginning. The built-in motorized calibration weight is applied and removed automatically for internal calibration.

- Select calibration/adjustment: Press (Cal)
- > The built-in weight is applied automatically
- > The balance/scale is adjusted
- > The built-in calibration weight is removed.

## Internal Calibration/Adjustment (Only on Models with a Built-in Motorized Calibration Weight)

Models with a resolution of 0.1 mg, ED...-CW, GK..., GW... models, and verified models (with the ...CE suffix) are equipped with a built-in motorized calibration weight as a standard feature

#### Set the following parameters:

SETUP: BALSCAL.: CAL.-ADJ.: CAL.INT. (menu code 1.1.9.4)

The built-in motorized calibration weight is applied and removed automatically for internal calibration.

	Step	Key (or instruction)	Display
1.	Tare the balance/scale	Tare	0.0 g
2.	Start calibration	Cal	CAL.INT.
	The built-in weight is applied automatically		CAL.RUN.
3.	Calibration/adjustment executed		CAL.EN]
4.	The built-in weight is removed		0.0 g

15

#### **External Calibration**

Parameters (changes in factory settings):

SETUP: BAL.SCAL.: CAL.-ADJ.: CAL.EXT. (menu code 1.1.9.1)

The required calibration weight is configured at the factory (see "Specifications")

Step	Key (or instruction)	Display
1. Tare the balance/scale	Tare	0.0 g
2. Start calibration.	Cal	CAL.EXT.
Once you store the zero point the required calibration weight is prompted (flashing display)		- 5000.0 g
3. Apply the prompted calibration weight (in this example: 5000 g) Weight too light: a minus sign "-" is shown Weight too heavy: a plus sign "+" is shown	<del>-</del>	5000.0 g
The display stops flashing as soon as the weight value is within the defined limit.		
4. Calibration/adjustment executed;		CAL.ENI)
then the calibration weight is displayed		+ 5000.0 g
5. Remove the calibration weight	<u>†</u>	0.0 g

## **Configuration (Operating Menu)**

You can configure the balance/scale; i.e., adapt it to individual requirements.

### **Functions of the Keys during Configuration**

[••••]		Indicates menu level
<	CF	One menu level higher
<<	CF	Save settings and exit menu
	(press and hold)	Save settings and exit menu from any position
<u> </u>	Enter	Confirm menu item
>	Enter	One menu level lower
V	Select Menu	Scroll through menu items
Symbol	Key	Function

## Menu Navigation

Example: Setting the Language

Step	Key (or instruction)	Display
Open the menu:     In weighing mode: first menu item is shown	Select (hold)	APPLIC.
2. Scroll upward within the menu level; after the last menu code, the first code is displayed again	Repeatedly:	INPUT  LANGUAG.
3. Select menu level (scrolls to the right)	Enter	ENGLISH °
5. <b>Change setting:</b> Scroll until the desired setting is shown	<u>Select</u> Menu	ESPANOL
6. <b>Confirm the menu code</b> ; "o" indicates the active setting	Enter	ESPANOL °
<ul><li>7. Return to the next higher menu level (from the fourth level)</li><li>O Set other menu items as desired</li></ul>	CF Select Menu , Enter	LENGUA
8. Save settings and exit menu	Repeatedly:	ONX  CHYLOLOGY  CHYLOL
or		
○ Exit menu without saving changes	(I/Ú)	
> Restart your application		0.0 g

## Parameter Settings: Menu

Level 1 [•	] Level 2 [•• ]	Level 3 [••• ]	Menu code
SETUP	T BALSCAL. ———	AMBIENT Ambient conditions	1. 1. 1.
	Balance/scale parameter	s #PP.FILT. Application filter	1. 1. 2.
		STABLENG. Stability range	1. 1. 3.
		⊢ IHRIN⊓ Tarinα	1. 1. 5
		—— RUTOZER. Auto zero	1. 1. 6
		WT.UNIT Basic weight unit	1. 1. 7.
		── #15PLHY Display accuracy	1. 1. 8.
		H /H /H / Function of the (Cal.) key	1. 1. 9.
		EALUNIT Weight unit for calibration	1. 1. 11.
	— INTERF.Interface —	BAUD Baud rate	1. 5. 1.
		—— PARITY Parity	1. 5. 2.
		— STOPBIT Number of stop bits	1. 5. 3.
		— HANDSHK Handshake mode	1. 5. 4.
		— BATABIT Number of data bits	1. 5. 5.
		IAT.REE. Output: SBI (ASCII) or printout	1. 5. 6.
	PRNT.OUT -		1. 6. 1.
	Settings for print function	on STUPHUL. Stop automatic printing	1. 6. 2.
			ing 1. 6. 3.
		—— THR./PRT. Tare bal./scale after ind. print	1. 6. 4.
		TAR./PRT. Tare bal./scale after ind. print PRT.INIT. Printout of appl. parameters	1. 6. 5.
			1. 6. 6.
		— □LP ISO/GLP-compliant printout	1. 6. 7.
		SLP ISO(GLP-compliant printout  TIME: 12/24 h	1. 6. 8.
		— ∌H≀E: Format	1. 6. 9.
	— EXTRAS	MENU	1. 8. 1.
	Additional functions	— 515NAL Acoustic signal (beep)	1. 8. 2.
		— KEYS Keypad	1. 8. 3.
		- EXTLIET External switch function	1. 8. 4.
		ON MODE Power-on mode	1. 8. 5.
	L RESET -	Hi Ki   Display backlighting	1. 8. 6.
	- HEZE! -	MENU Factory settings	1. 9. 1.
APPLIC. ——	WEIGH	### ##################################	2. 1.
Application	UNIT Toggle wt. unit -	■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■	2. 2. 2.
programs	EDUNT, Counting —	RESOLUT, Resolution	2. 3. 1.
p 3		REFUENT, Autom, ref. sample updating	2. 3. 2.
	PERCENT Weighing in p	ercent — IEC.PLES Decimal places	2. 4. 1.
	── NET-TOT Net-total form	nulation — EDMP.PRT. Printout of components	2, 5, 1,
	— TOTAL Totalizing —	======================================	2, 6, 1,
	- ANIMALW, Animal weight	ing ————————————————————————————————————	2, 7, 1,
		└─ START	2. 7. 2.
	— EALE. Calculation ——	METHOD (operator)	2. 8. 1.
		START  METHOD (operator)  EE.P.LES Decimal places	2. 8. 2.
	— IENSIII Density detern	nination — IEE.PEES Decimal places	2. 9. 1.
		ID input; max. 7 characters	3. 1.
INFO Informati	on — VERSION, SER.NO., MOD	Display software ver., serial no., model	4. 1./.2./.3.
LANGUAG. —	ENGLISH (factory setting	a)	5. 1.
		-	5. 2.
	FRANC French		5. 3.
	— ITAL. Italian		5. 4.
	ITAL. Italian ESPANOL Spanish COJES Menu shows cod		5. 4. 5. 5.

# **Parameter Settings: Overview** o = Factory setting $\sqrt{\ }$ = User-defined setting

Level 1	Level 2 ┃••	Level 3	Level 4	Menu code
SETUP	BAL.SEAL.  Balance/scale parameters	Ambient o conditions (Filter adaptation)	V.STABLE Very stable STABLE UNSTABL V.UNSTBL. Very unstable	1. 1. 1. 1 1. 1. 1. 2 1. 1. 1. 3 1. 1. 1. 4
		-	F INAL.R.B. Final readout mod F ILL ING Filling mode	le 1. 1. 2. 1 1. 1. 2. 2
		Stability range o	I/4 DIG. (digit) I/2 DIG. I - DIGIT 2 - DIGIT 4 - DIGIT 8 - DIGIT	1. 1. 3. 1 1. 1. 3. 2 1. 1. 3. 3 1. 1. 3. 4 1. 1. 3. 5 1. 1. 3. 6
		- TARING 1) o	W/O STBW/o stability) W/ STAB After stability)	1. 1. 5. 1 1. 1. 5. 2
		Auto zero o	OFF ON	1. 1. 6. 1 1. 1. 6. 2
		Basic weight through unit	For list of units, see "Toggling between Weight Units"	1. 1. 7. 1 1. 1. 7. 23
		O Display accuracy	ALL MINUS   ) BIVIS.  1 interval )	1. 1. 8. 1 1. 1. 8. 2 1. 1. 8. 6
		O Function of the Cal key	EAL.EXT. External cal./adj. EAL.INT. Internal cal./adj. <sup>2</sup> ) BLOCKED (a) key blocked	1. 1. 9. 1 1. 1. 9. 2 1. 1. 3. 3
		- EAL.UNIT. Unit <sup>1</sup> ) o for calibration weight	GRAMS KILOGR. Kilograms POUNDS	1. 1.11. 1 1. 1.11. 2 1. 1.11. 3

<sup>1)</sup> Setting cannot be changed on verified balances/scales

<sup>&</sup>lt;sup>2</sup>) Only on models with built-in motorized calibration weight

Level 1	Level 2 ●●	Level 3	Level 4	Menu code
SETUP —	INTERF.	BRUD rate — o	600 1200 2400 4800 9600 19200	1. 5. 1. 3 1. 5. 1. 4 1. 5. 1. 5 1. 5. 1. 6 1. 5. 1. 7 1. 5. 1. 8
		Parity o	ODD EVEN NONE	1. 5. 2. 3 1. 5. 2. 4 1. 5. 2. 5
	_	— STOPBIT — o No. of stop bits — o	IBIT 2 BITS	1. 5. 3. 1 1. 5. 3. 2
		HANDSHK. — o mode	SFTWARE HR]WARE NONE	1. 5. 4. 1 1. 5. 4. 2 1. 5. 4. 3
		— DATABIT — o No. of data bits	TBITS BBITS	1. 5. 5. 1 1. 5. 5. 2
		— DAT.REE. Com- munication mode — o	SBI (ASCII) PRINTER (GLP-printout)	1. 5. 6. 1 1. 5. 6. 2
	PRNT_OUT Printing fct.	— PRINT ————————————————————————————————————	MRN. W/O W/o stability MRN.WITH W/ stability RUT.W/O Autom. w/o stability RUT.WITH. Autom. w/ stability	
		— STOPAUT. Stop — o automatic printing	OFF Not possible ON Use print key 🗐	1. 6. 2. 1 1. 6. 2. 2
		— AUT.EYEL. — o Time-dependent autom. printing	EREHVAL (1 display update) AFTER 근 (2 display updates)	1. 6. 3. 1 1. 6. 3. 2
		the bal./scale after individual printout	OFF ON	1. 6. 4. 1 1. 6. 4. 2

Level 1	Level 2 【◆◆ 】		Level 3		Level 4 [••••]	Menu code
SETUP ——	PRNT.OUT — Printing fct.		PRT.INIT.  Printing application parameters	o	OFF ALL All parameters MAINPAR. Main parameters	1. 6. 5. 1 1. 6. 5. 2 1. 6. 5. 2
			FORMAT Line format for printout	o	I6 CHAR. 16 characters (w/o ID) 22 CHAR. 22 characters (w/ ID)	
			SLP Printout as ISO/GLP- compliant TIME	O	OFF EALAJJ. Only for calib./adj. ALWAYS All printouts 24 H 24-hour format H2 H 12-hour format "AM/PM" BJ.MM.YY Day/month/year MM.JJ.YY Month/day/year	1. 6. 7. 3 1. 6. 8. 1
	EXTRAS Additional functions		MENU 1)	o	EANE IIT Can change settings RI. ONLY Read only	1. 8. 1. 1 1. 8. 1. 2
		_	SIGNAL Acoustic signal	o	OFF ON	1. 8. 2. 1 1. 8. 2. 2
		_	KEYS Keypad	0	FREE LOCKED	1. 8. 3. 1 1. 8. 3. 2
			Function of the external switch	0	PRINT (F) 2/TARE Tare EAL. Enter SELECT Steel ENTER Enter	1. 8. 4. 1 1. 8. 4. 2 1. 8. 4. 3 1. 8. 4. 4 1. 8. 4. 5 1. 8. 4. 6
			ON MODE Power-on mode	o	OFF /ON Off/on/standby STANDBY On/standby AUTO ON Auto on	1. 8. 5. 1 1. 8. 5. 2 1. 8. 5. 3
			BACKLIT Display backlighting	o	OFF ON	1. 8. 6. 1 1. 8. 6. 2
	RESET Reset menu	_	MENU ————————————————————————————————————	o	Restore fety. settings  NO Do not restore settings	1. 9. 1. 1 1. 9. 1. 2

<sup>&</sup>lt;sup>1</sup>) Setting cannot be changed on verified balances/scales

Level 1	Level 2 ┃••	Level 3	Level 4	Menu code
APPLIC. — Applic. programs	— WEI5H — UNIT ——— Toggle units	DISP.DIS. o Display accuracy	ALL MINUS +1) BIVIS. +1 interval	2. 1. 2. 2. 2. 1 2. 2. 2. 2 2. 2. 2. 6
	— COUNTING —	RESOLUT. — o Resolution	<pre>BISP.ACC. Display accuracy IO−FOL B 10 times &gt; disp.</pre>	2. 3. 1. 1 2. 3. 1. 2
		REF.UPIT. o Autom. reference updating	OFF AUTO	2. 3. 2. 1 2. 3. 2. 2
	— PEREENT —— Weighing in percent	DEC.PLES o	NONE No dec. places I BEC.PL. 1 decimal place BEC.PL. 2 decimal places BEC.PL. 3 decimal places	2. 4. 1. 1 2. 4. 1. 2 2. 4. 1. 3 2. 4. 1. 4
	— NET-TΩT —— Net-total	Component o printout	OFF ON	2. 5. 1. 1 2. 5. 1. 2
	— TOTAL ——— Totalizing	COMP.PRT. o printout	OFF ON	2. 6. 1. 1 2. 6. 1. 2
	— ANIMALW. Animal weighing	ACTIVIY. — o	EALM Fluct.: 2% of test obj.) ACTIVE (fluct.: 5% of test obj.) V.ACTIVE(fluct.: 20% of test obj.)	2. 7. 1. 2
		STARTo	MANUAL AUTO. Automatic	2. 7. 2. 1 2. 7. 2. 2
	— CALC. ————————————————————————————————————	METHOD o (operator)	MUL. Multiplier BIV. Divisor	2. 8. 1. 1 2. 8. 1. 2
		DEC.PLES o places	NONE No dec. places I DEE.PL.1 decimal place 2 DEE.PL.2 decimal places 3 DEE.PL.3 decimal places	2. 8. 2. 1 2. 8. 2. 2 2. 8. 2. 3 2. 8. 2. 4
L	— BENSITY —— Density determination	Decimal places o	NONE No dec. places 1 BEE.PL.1 decimal place	2. 9. 1. 1 2. 9. 1. 2

<sup>&</sup>lt;sup>1</sup>) Setting cannot be changed on verified balances/scales

### ID Number for ISO/GLP-compliant Data Record

Level 1	Level 2	Level 3	Menu code
[• ]	[•• ]	[••• ]	
INPUT —	—— ID NO.——	— ID input; max. 7 characters	3. 1.
Input		Permitted characters: 0 to 9; A to Z;	
		dash/hyphen; space	

### **Function of the Keys when Entering ID Numbers**

Select key: Press and hold to repeat					
Display	Key	Display symbol	Function		
	First position:				
ID 12534	Enter	>	Go to next position		
**************************************	Select Menu	V	Select current position		
	CF	<<	Exit without saving changes		
	Middle positions:				
III (7534	Select Menu	V	Select current position		
11, (21,	Enter	>	Go to next position		
	CF	<	Go to previous position		
	Last position:				
T 11 175 34	Select Menu	V	Select current position		
TT 1.127	CF	<	Go to previous position		
	Enter	<b>₊</b>	Store and exit		

#### **Device Information**

Level 1	Level 2 [•• ]	Level 3 <b>[•••</b> ]	Example	Menu code	
INFO —	— VERSION —	- Show software version	REL.32.02	4. 1.	
Information	— SER. NO.  ——	- Show serial number (To toggle focus between upper and lower display sections, press (Menu)	1080 1234	4. 2.	
	— MOJEL ——	- Show model designation (to change focus from upper to middle to lower display section and back, press	25059E3	4. 3.	
Display of Menu Items: Text or Codes					
LANGUAG. — ENGLISH (factory setting) — DEUTSCH German — FRANC. French — ITAL. Italian — ESPANOL Spanish — CODES Menu shows codes (not texts)				5. 1. 5. 2. 5. 3. 5. 4. 5. 5. 5. 6.	

## **Application Programs**

## Counting

Display symbol: ...

#### Purpose

With the Counting program you can determine the number of parts that each have approximately equal weight. To do this, a known number of parts (the reference sample quantity) is weighed first, and the individual piece weight (reference weight) is calculated from this result. Thus the number of parts subsequently placed on the balance/scale can be determined from their weight.

#### Changing the Reference Sample Quantity Activate function:

Press the Select key

Select the desired reference sample quantity (1 to 100):

In increments of 1: Press the (Select Menu) key briefly

In increments of 10:

Press and hold the Select key.

The quantity is stored in battery-backed memory.

#### Reference Sample Updating

Automatic reference sample updating optimizes the counting accuracy. You can activate or deactivate this function in the menu.

Automatic reference sample updating is performed when the requirements, including the specified stability criterion, have been met.

The abbreviation  $\Box PT$ , for "optimizing", is displayed briefly with the new reference sample quantity.

#### **Preparation**

- Select the Counting application in the menu: see "Configuration."
- Set the following parameters:

APPLIE. Application program

```
COUNT.
   RESOLUT. Resolution
      - o IISP.ACC. Display accuracy
           □-F□L  10-fold higher
    REF.UPIT. Autom. ref. sample
              updating
      - o OFF
                     Display accuracy
           AUTOM.
                     Automatic
o = Factory setting
```

#### **Printout: Counting**

nRef : Reference sample quantity : Reference weight wRef + 21.14 g Qnt 500 pcs: Calculated quantity

**Example:** Counting parts of equal weight Parameter settings: APPLIE.: EQUNT. (menu code 2. 3.)

Step	0	Key (or instruction)	Display/Data output		
1.	Place empty container on the balance/scale		+ 22.5 g		
2.	Tare the balance/scale	Tare	0.0 g		
3.	Add reference sample quantity to container (in this example: 20 pcs)	*			
4.	Changing the reference sample quantity:	Select Menu	REF IDpcs		
5.	Select reference sample quantity: In increments of 1 (1, 2, 3, etc. to 100) In increments of 10 (10, 20, etc. to 100)	Repeatedly: Select Menu Press briefly Select Menu press and hold	REF 20pcs		
6.	Confirm selected reference sample quantity and start application The current reference weight remains stored until a new reference is set or the power supply is interrupted	Enter	+ 2⊕pcs nRef 20 pcs wRef 1.07 g		
7.	Add desired number of pieces	<b>*</b>	+ 500pcs		
8. 9.	If desired, print quantity Toggle display between mean piece weight, weight, quantity	Repeatedly: Select Menu	Qnt + 500 pcs 1.07 g * + 535.0 g * + 500pcs *		
	Unload the balance/scale  Repeat as needed, starting from Step 7	*	– 2 lpes *		
12.	Delete reference value	CF	0.0 g		

## **Weighing in Percent**

Display symbol: %

#### **Purpose**

This application program allows you to obtain weight readouts in percent which are in proportion to a reference weight.

#### **Changing the Reference Percentage**

Activate function:

Press the Select key

Select the desired reference (1 to 100): In increments of 1: Press the Select key


briefly

In increments of 10: Press and hold the

The percentage is stored in battery-backed memory.

#### **Preparation**

- Select the Weighing in percent application in the menu: see "Configuration."
- Set the following parameters:



o = Factory setting

#### **Printout: Weighing in percent**

pRef		100		: Reference
Wxx%		111.6	g	percentage : Reference weight net xx% for selected
Prc	+	94.9	pcs	reference percentage : Calculated reference percentage

**Example:** Determining residual weight in percent Parameter settings: APPLIE.: PERCENT (menu code 2. 4.) Reference percentage: REF 100%

Step	Key (or instruction)	Display/Data output		
<ol> <li>Tare the balance/scale</li> <li>Information:         <ul> <li>Enter reference percentage</li> <li>(Changing the reference: see the previous page)</li> </ul> </li> </ol>	Tare Select Mem	REF	0.0 g 100 %	
3. Place sample equal to 100% on the balance/scale (in this example: 111.6 g)	<b>—</b>			
4. Initialize the balance/scale The current reference weight remains stored until a new reference is set or the power supply is interrupted	Enter	+ pRef Wxx%		
5. Remove sample (e.g., for drying)	<u> </u>			
6. Place unknown weight on balance/scale (in this example: 322.5 g)	<b>—</b>	+	94.9 % *	
7. If desired, print percentage		Prc	+ 94.9 %	
8. Toggle display between weight and percentage	Repeatedly: Select Menu	++	105.9 g <sub>*</sub> 94.9 % <sub>*</sub>	
<ol><li>Clear display of residual weight and reference percentage</li></ol>	CF	+	105.9 g	
10. If desired, print net residual weight	<b>a</b>	N	+ 105.9 g	

## Calculation

#### Display symbol: C

#### **Purpose**

With this application program you can calculate weight value using a multiplier or divisor. This can be used, for example, to determine the weight per unit area, or "gsm" weight (grams per square meter), of paper.

#### **Setting the Factor or Divisor**

Activate function:

Press the Select key

Select a number of up to 7 digits and, if needed, one decimal point (0.000001 to 9999999):

In increments of 1: Press the (Menu) key briefly

To increase the value without pressing repeatedly:

Press and hold the Select key.

The selected operator is stored in battery-backed memory.

#### Preparation

- Select the Calculation application in the menu: see "Configuration."
- Set the following parameters:

#### Printout: Calculation

o = Factory setting

Mul	+	1.2634		: Multiplier
Div	+	0.6237		: Divisor
Res	+	79.7	О	: Result

#### Example:

Calculating the weight per unit area of paper: An A4 sheet of paper is used in this example, with surface dimensions of  $0.210 \text{ m} \times 0.297 \text{ m} = 0.06237 \text{ m}^2$ . To determine the weight per unit area, the total weight is divided by the surface.

#### Parameter settings:

APPLIC.: EALE..: METHOD: DIV. (menu code 2. 8. 1. 2)

Key (or instruction)	Display/Data output		
Tare		0.00 g	
Select Menu		0.	
P):  Enter, 5x (Menu), 2x (Enter), Repeatedly or press and hold; (Select), (Enter), etc.		00000 06000 06237	
Enter	+ Div	0.0 ° 0.6237	
<b>—</b>	+	79.7 ° *	
	Res	+ 79.7 o	
Repeatedly: Select Menu	++	4.97g * 79.7° *	
<u>†</u>	+	0.0 ° *	
	Tare  Select Menu  Them, 5x Select Menu  Them, 5x Select Menu  Them, 5x Select Menu  Them, 6x Select Menu  The	Tare  Scient Menu  Tare  Tare  Scient Menu  Tare  Tare  Tare  Tare  Scient Menu  Tare  T	

## **Animal Weighing/Averaging**

Display symbol: 🕰

#### **Purpose**

Use this program to determine the weights of unstable samples (e.g., live animals) or to determine weights under unstable ambient conditions. With this program, the balance/scale calculates the weight as the average of a defined number of individual weighing operations (also referred to as "subweighing operations").

## Changing the Number of Subweighing Operations

Activate function:

Press the Gelect key

Select the desired number of measurement (1 to 100):


In increments of 1: Press the key briefly

In increments of 10: Press and hold the

The selected number of measurements is stored in battery-backed memory.

#### Preparation

- Select the Animal weighing application in the menu: see "Configuration."
- Set the following parameters:



#### Printout: Animal weighing

mDef		20		: Number of sub-
				weighing operations
x-Net	+	410.1	g	: Calculated average

**Example:** Determining animal weight with automatic start and 20 subweighing operations (measurements)

Parameter settings: APPLIE.: ANIMALW. (menu code 2. 7.)

Next weighing series begins automatically

Step	Key (or instruction)	Display/Data output
Place animal weighing bowl on the balance/scale	<u></u>	22.6 g
2. Tare the balance/scale	Tare	0.0 g
3. Change the number of subweighing operations:	Select Menu	REF 30
4. Set number of measurements: In increments of 1 (1, 2, 3, etc. to 100) In increments of 10 (10, 20, etc. to 100)		REF 20
5. Confirm number of measurements and start automatic animal weighing The number of measurements remains stored in battery-backed memory until the setting is changed	Enter	+ 0.0 g <sub>*</sub>
6. Place first animal in bowl.  The balance/scale delays the start of measurements until the difference between 2 measurements meets the criterion	<u></u>	888 20 19 
7. Read off the result The result is displayed with the "*" symbol (= calculated value) and remains displayed until the sample (animal) is removed from the load plate (bowl)	_	+ Ч ¦□.   g <u>∧</u> *  m Def 20 x-Net + 410.1 g
8. Unload the balance/scale	<u></u>	+ 0.0 g <sub>*</sub>
9. Weigh next animal (if des.)		

33

### **Net-total Formulation**

#### Display symbol: Ł

#### **Purpose**

With this application program you can weigh in different components up to a defined total. You can print out both the total weight and the individual weights of the components.

#### **Features**

- Weigh up to 99 components from "0" to a defined total component weight.
- Store component weights ("Store xx comp."), with
  - display zeroed automatically after value is stored, and
  - automatic printout
- Clear component memory following cancellation of the weighing sequence (by pressing CF) and printout of the total weight.
- Toggling between component weight and total weight by pressing and holding (< 2 sec).</li>
- Printout of the total of the individual component weights (T – C o m p)

#### **Preparation**

- Select the Net-total application in the menu: see "Configuration."
- Set the following parameters:

### o = Factory setting

#### **Printout: Net-total formulation**

Comp 2+ 278.1 g : Second component
T-Comp+ 2117.5 g : Sum of components

### **Example:** Counting parts into a container

Parameter settings: RPPLIC.: NET-TOT (menu code 2. 5.)

Step	Key (or instruction)	Display/Data output
Place empty container on the balance/scale.	<u></u>	65.0 g
2. Tare the balance/scale	Tare	0.0 g
3. Add first component	<b>—</b>	+ 120.5 g
4. Store component data	Enter	+
5. Add next component	<u></u>	+ 70.5 g <sub>*</sub> NET
6. Store component data	Enter	+ $0.0 \text{ g} * NET$ Comp 2+ 70.5 g
7. Weigh in further components as desired	Repeat steps 5 and 6	
8. Fill to desired final value view the current total weight value:	<u>Select</u> <u>Menu</u>	+ 191.0g <sub>*</sub>
9. Print total weight and clear the component memory	CF	+ 2117.5 g T-Comp+ 2117.5 g

35

## **Totalizing**

Display symbol: Ł

#### **Purpose**

With this application program you can add values from successive, mutually independent weight values to a total that exceeds the capacity of the balance/scale.

#### **Features**

- Totalizing memory for up to 99 values
- Store component weights ("Store xx comp."), with automatic printout
- Toggle display between the current individual weight value and the value in totalizing memory by pressing
- Printout of the total of the individual component weights (S – C omp)
- To close the application program and print the total weight: press (CF)

#### Preparation

- Select the Totalizing application in the menu: see "Configuration."
- Set the following parameters:

```
### RPPLIE. Application program

TOTAL Totalizing

EDMP.PRT. Printout of components

OFF

ON
```

o = Factory setting

#### **Printout: Totalizing**

Comp 2+ 278.1 g : Second component S-Comp+ 2117.5 g : Totalizing memory

## **Example:** Totalizing weight values

Parameter settings: APPLIC.: TOTAL: COMP.PRT: ON (menu code 2. 6. 1. 2)

Step	Key (or instruction)	Display/Data output
1. Tare the balance/scale	Tare	0.0 g
2. Place sample balance/scale (in this example: 380 g)	<b>—</b>	+ ∃80.0 g
3. Store value in memory	Enter	+ ∃80.0 g <sub>*</sub> Comp 1+ 380.0 g
4. Remove sample	<u></u>	+ 0.0 g <sub>*</sub>
5. Place the next sample on the balance/scale (in this example, 575 g)	<b>—</b>	+ 575.0g <sub>*</sub>
6. Store value in memory	Enter	+ 955.0 g * + 575.0 g * Comp 2+ 575.0 g
7. View the value in totalizing memory	Select Menu	+ 955.0 g <sub>A*</sub>
8. Weigh in further components as desired	Repeat steps 5 and 6	
9. Print total weight and clear the totalizing memory	CF	0.0 g S-Comp+ 2117.5 g

### **Mass Unit Conversion**

#### **Purpose**

With this application program you can change the weight value displayed from the basic weight unit to any of 4 application weight units (see table on next page).

#### **Features**

- Set the basic unit and display accuracy in the Setup menu: see "Configuration."
- Set the application weight units and display accuracies in the Application menu.
- These settings are stored in battery-backed memory.
- The basic unit is active when the balance/scale is powered up.

**Example:** Change display from the basic unit (in this example, grams [g]) to pounds [lb] and then to Troy ounces [ozt].

Set the following parameters: APPLIE.: UNIT (code 2. 2.)

	Step	Key (or instruction)	Display/D	ata output
1.	Begin selection of an application weight unit	<u>Select</u> Menu	NONE	0
2.	Select an application unit; in this example, pounds (see table on next page)	Repeatedly:	POUNDS	
3.	Confirm the weight unit (pounds)	Enter	POUNIS	0
4.	Select the next application weight unit;		NONE	0
	in this example: Troy ounces (see table on next page)	Repeatedly:  Select Menu	TROY OZ	
5.	Confirm weight unit (Troy ounces)	Enter	TROY OZ	. 0
6.	Select other application units if desired (max. 4 total) (otherwise, confirm NONE by pressing Enter)			
7.	Store selection	CF	0.0	70 g
8.	Place sample on balance/scale	<b>*</b>	+ 100.0	00 g
9.	Change unit for weight value	Repeatedly:	+ 0.220 <sup>4</sup> + 3.52	

The following weight units are available in your Extend balance/scale (in legal metrology, only units permitted by national law are available):

Menu item	Unit	Conversion factor	Display symbol
1) USERDEF. 1)	Grams	1,0000000000	0
2) GRAMS (Factory setting)	Grams	1.00000000000	g
3) KILOGR.	Kilograms	0.00100000000	kg
4) CARATS	Carats	5.00000000000	0
5) POUNDS	Pounds	0.00220462260	lb
6) DUNCES	Ounces	0.03527396200	OZ
<b>7)</b> TROY OZ.	Troy ounces	0.03215074700	ozt
8) HKTAEL	Hong Kong taels	0.02671725000	tl
9) SNG.TAEL.	Singapore taels	0.02645544638	tl
10) TWN.TAEL	Taiwanese taels	0.02666666000	tl
11) GRAINS	Grains	15.4323583500	GN
12) PENY.WT.	Pennyweights	0.64301493100	dwt
13) MILLIGR.	Milligrams	1000.00000000	mg
14) PT.P.L B.	Parts per pound	1.12876677120	0
15) CHN.TREL	Chinese taels	0.02645547175	tl
16) MOMMES	mommes	0.26670000000	m
17) AUSTR.ET.	Austrian carats	5.00000000000	Kt
18) TOLA	Tola	0.08573333810	0
19) BAHT	Baht	0.06578947436	b
20) MESGHAL	Mesghal	0.21700000000	0
21) TONS	Tons	0.00000100000	t
22) L B / OZ <sup>2</sup> )	Pounds: ounces	0.03527396200	lb oz
23) NEWTON	Newton	0.00980665000	N

<sup>1) =</sup> User-defined weight unit; can be loaded in the balance/scale over an optional RS-232 or USB interface using a computer program.

Some weight units may be blocked from use in legal metrology, depending on national verification laws.

<sup>&</sup>lt;sup>2</sup>) = The format for display of pounds/ounces cannot be changed: xx:yy.yy x=lb, y=oz

## **Density Determination**

Display symbol: ΔΔ

#### **Purpose**

This application program lets you determine the density of solid substances using the buoyancy method. You can have results displayed with one decimal place, or no decimal places: see "Configuration."

Note: the sample holder and suspension wire used in the example below are not included with the balance/scale.

#### Parameter settings:

APPLIE.: DENSITY: DEE.PLES: | DEE.PL. (menu code 2. 9. 1. 2)

**Example:** Determining the density of a solid sample.

13. Repeat as desired, starting from Step 3.

Step	)	Key (or instruction)	Displ	ay/Data o	utput	
1.	Attach sample holder to suspension wire					
2.	Tare the balance/scale	Tare		0.0 g		
3.	Start application program	Enter				
4.	Confirm "AIR" display	Enter	AIR	?		
5.	Determine the weight of the sample in air: Place sample on the balance/scale	<u></u>	+	20.0 g <sub>*</sub>		
6.	Store value for weight in air	Enter				
7.	Remove sample from the balance/scal	e	WATE	ER ?		
8.	Determine weight in liquid: place sample in holder	mann mann				
9.	Confirm "WATER" display	Enter		0.0 g <sub>*</sub>		
10.	Immerse sample in liquid		+	15.0 g <sub>*</sub>		
11.	Store value for weight in liquid, view result, and print	Enter	+ Wa Wfl Rho	4.∏ ° + +	20.0 15.0 4.0	g
12.	Delete result	CF				

## ISO/GLP-compliant Printout/Record

#### **Features**

You can have device information, ID texts and date and time printed before (GLP header) and after (GLP footer) the values of a weighing series. These parameters include:

#### GLP header:

- Date
- Time at beginning of measurement
- Balance/scale manufacturer
- Balance/scale model
- Balance/scale serial number
- Software version number
- Identification number of the current sampling operation

#### GLP footer:

- Date
- Time at end of measurement
- Field for operator signature

# ∴ Operating the Balance/Scale with a Verifiable ISO/GLP Printer:

 Connect a Sartorius data printer designed for ISO/GLP documentation (e.g., the YDP03-0CE printer) to the balance/scale.

#### Configuration

- Setting menu codes for the printout (see "Configuration"):
- ISO/GLP-compliant printout or record only for calibration/adjustment: SETUP: PRNT.DUT: GLP: EAL.-ADJ. (menu code 1. 6. 7. 2) or ISO/GLP-compliant printout or record always on: SETUP: PRNT.DUT: GLP: ALWAYS DN (code 1. 6. 7. 3)
- Line format for printout: include data ID codes (22 characters; factory setting): SETUP: PRNT.DUT: FORMAT: 22 CHAR. (menu code 1. 6. 6. 2)

- Formats for time:
  SETUP: PRNT.DUT: TIME: 24H
  (menu code 1. 6. 8. 1) or
  SETUP: PRNT.DUT: TIME: 12H
  (menu code 1. 6. 8. 2)
- Formats for date: SETUP: PRNT.OUT: DATE: DD.MMM.YY (menu code 1. 6. 9. 1) or SETUP: PRNT.OUT: DATE: MMM.DD.YY (menu code 1. 6. 9. 2)
- if any of the following settings are configured:
  SETUP: PRNT.OUT PRINT: AUT.W/O or AUT.WITH (menu code 1. 6. 1. 3, 1. 6. 1. 4,) or FORMAT: 15 EHAR. (menu code

♠ No ISO/GLP-compliant record is output

#### **Function Keys**

1. 6. 6. 1)

Transfer header and first measured value: press (  $\blacksquare$  )

> The header is included with the first printout/data record.

To output header and reference data automatically when an application program is active: press (Enter)

Exit the application:

- 1) To send the GLP footer: press (CF)
- 2) Quit application program: press CF again

#### The ISO/GLP-compliant printout can contain the following lines:

17-Aug-2005 10:15
SARTORIUS
Mod. ED8201
Ser. no. 10105355
Ver. no. 00-32-02
ID 2690 923
L ID
nRef 10 pcs
wRef 21.14 g
Qnt + 567 pcs
17-Aug-2005 10:20
Name:

Dotted line Date/time (beginning of measurement) Balance/scale manufacturer Model Balance/scale serial number Software version ID. Dotted line Measurement series no. Counting: reference sample quantity Counting: reference weight Counting result Dotted line Date/time (end of measurement) Field for operator signature Blank line Dotted line

### ISO/GLP-compliant printout for external calibration/adjustment:

Dotted line

17-Aug-2005 10:30
SARTORIUS
Mod. ED8201
Ser. no. 10105352
Ver. no. 00-32-02
ID 2690 923
2070 725
Cal. Ext. Test
Set + 5000.0 g
Diff. + 0.2 g
Cal. Ext. Complete
Diff. 0.0 g
17-Aug-2005 10:32
Name:

Dotted line Date/time (beginning of measurement) Balance/scale manufacturer Model Balance/scale serial number Software version 1D. Dotted line Calibration/adjustment mode Calibration weight Difference determined in calibration Confirmation of completed calibration procedure Difference from target following adjustment Dotted line Date/time (end of measurement) Field for operator signature Blank line

### **Interface Port**

#### **Purpose**

Your balance/scale is equipped with an interface port for connection to a computer or other peripheral device.

You can connect a computer to change, start and/or monitor the functions of the balance/scale and the application programs.

#### **Features**

Type of interface: Serial interface Operating mode: Full duplex

Standard: RS-232 Transmission rates: 600, 1200, 2400, 4800, 9600 and 19,200 baud Parity: odd, even, none

Number of data bits: 7 or 8 bits

Character format:

1 start bit, 7-bit ASCII, parity, 1 or 2 stop bits

Handshake: For 2-wire interface: software (XON/XOFF) For 4-wire interface: hardware (CTS/DTR)

Data output format of the balance/scale:

16 or 22 characters

#### **Factory Settings**

Transmission rate:

1200 baud (menu code 1. 5. 1. 4)

Parity: [1] [1. 5. 2. 3]

Stop bits: /570P bit (1. 5. 3. 1)

Handshake:

HANDSHK. Hardware, (1. 5. 4. 2)
Operating mode: PRINTER (1. 5. 6. 2)
printing: MAN.WITH Manual after stability

(1.6.1.2)

#### **Preparation**

See "Pin Assignments" and "Pin Assignment Chart"

#### **Identification of Non-Verified Digits**

To have non-verified digits (when "e # d") automatically identified on the printout, set the following parameters: Communication: PRINTER (menu code 1. 5. 6. 2) Non-verified digits are marked by square brackets [].

### **Data Output Format with 16 Characters**

Display segments that are not activated are output as spaces.

The type of character that can be output depends on the character's position:

Position	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	+			D	D	D	D	D	D	D	*	U	U	U	CR	LF
or	_											*	*	*		
or	*		*	*	*	*	*	*	*	*						
*:	Sp	ace						CR:		Carria	ge re	turn				
D:			lette					LF:		Line f						
U:	Un	it sy	mbol					.:		Decin	ial po	oint				
C	1															
Special Co		2	2	4	_	_	7	0	0	10	1.1	10	10	1.4	1 -	1.6
Position	_1_	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	*	*	*	*	*	*	*	*	*	*	*	*	*	*	CR	LF
or						Н	i	g	h							
or						L	0	W								
or				C	a	1		Е	х	t						
*:	Sp	ace						Higl	n:	Overlo	oad					
Cal. Ext.:	Ca	librat	tion,	exter	nal			Low	:	Unde	rload					
Error Code		0	0		_	_	-			10		10	10			1.6
Position	_1_	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
				Е	r	r	*	#	#	#	*	*	*	*	CR	LF
				Α	P	P		Е	R	$R^1$ )	*	*	*	*	CR	LF
				D	1	S		Е	R	R1)	*	*	*	*	CR	LF
				Р	R	Т		Е	R	R1)	*	*	*	*	CR	LF
*•	Sp	ace						# #	#:	Error	numl	oer				

<sup>&</sup>lt;sup>1</sup>) See "Troubleshooting Guide"

Example: Output of the weight value +123.56 g

Position 10 11 12 13 14 15 16 \* \* \* 1 2 3 6 CR LF 5 q \* \* 1 2 3 5 6 ]1) CR LF q

Position 1: Plus or minus sign or space

Position 2: Space

Weight with a decimal point; leading zeros = space Position 3–10:

Position 11: Space

Position 16:

Position 12–14: Unit symbol or space Position 15: Carriage return Line feed

#### **Data Output Format with 22 Characters**

When data is output with an ID code, the 6-character code precedes the 16-character string described above. The code identifies the subsequent value.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
1	1	1	1	1	1	+	*	D	D	D	D	D	D	D	D	*	U	U	U	CR	LF
	*	*	*	*	*	-											*	*	*		
						*		*	*	*	*	*	*	*	*						

1: 1D code character U: Unit symbol 1) \*: Carriage return CR: Space Digit or letter LF: Line feed D:

#### Example:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
N						+				1	2	3		5	6	*	g	*	*	CR	LF
N						+			1	2	3		5	[	6	]1)	g	*	*	CR	LF

#### 1) Identification of Non-Verified Digits

To have non-verified digits (when "e # d") automatically identified on the printout, set the following parameters: Communication: PRINTER (menu code 1. 5. 6. 2) Non-verified digits are marked by square brackets [].

### **Special Codes**

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
S	t	a	t	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	CR	LF
											Н	i	g	h							
											L	0	W								
									С	a	1		Е	х	t						

Overload

\*: Space High: Cal. Ext.: Calibration, external

Underload Low:

### **Error Codes**

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
S	t	a	t	*	*	*	*	*	Е	R	R	*	#	#	#	*	*	*	*	CR	LF
S	t	a	t	*	*	*	*	*	A	P	P		E	R	R1)	*	*	*	*	CR	LF
S	t	a	t	*	*	*	*	*	D	1	S		Е	R	R1)	*	*	*	*	CR	LF
S	t	a	t	*	*	*	*	*	Р	R	Т		Е	R	R1)	*	*	*	*	CR	LF

<sup>\*:</sup> Space

# # #:

Error code number

<sup>&</sup>lt;sup>1</sup>) See "Troubleshooting Guide"

#### **Commands (Data Input Format)**

You can connect a computer to your balance/scale to send commands via the balance/scale interface port for controlling balance/scale functions and applications. The commands sent are control commands and may have different formats. Control commands consist of up to 13 characters. Each character must be transmitted according to the settings configured in the operating menu for data transmission.

1 E

CD

#### Format for Control Commands

Ecc

Format 1:

Form	iat 1:	Esc	!		CR	LF			
Form	at 2:	Esc	!		#	_	CR	LF	
Esc: !:	Escape (c Comman Underline	d charact	er	CR: LF:	Carriage Line fee	return d (optiona	1)		
_	Comma	and chara	cter !	Form Mean	nat 1: ning				
			K	Amb	ient cond	itions: ver	y stable		
			L	Amb	ient cond	itions: stal	ole		
			M	Amb	ient cond	itions: uns	table		
			N	Amb	ient cond	itions: ver	y unstable		
			0	Block	k keys				
			P	(A)	key (prir	nt, auto pr	int; activate	or block)	
			R	Unbl	ock keys				
			S	Resta	art/self-te	st			
			T	Tare	key				
			W	Calib	ration/ad	justment (	depending o	on the menu setti	ng)
			Z	Inter	nal calibra	ation/adju	stment*		
	Comma	and chara	cter !#	Form Mean	nat 2: ning				
			f0_	Func	tion key	Select Menu			
			f1_	Func	tion key	CAL			
			f2_	Func	tion key	Enter			
			s3_	CF	key				
			x1_	Print	balance/	scale mode	el		
			x2_	Print	weighing	cell serial	number		
			x3_	Print	software	version			
* 0	nh, on mo	dala with	hil+	in	torized or	libration	waight		

<sup>\* =</sup> only on models with built-in motorized calibration weight

#### **Synchronization**

During data communication between the balance/scale and a connected device (computer), messages consisting of ASCII characters are transmitted via the interface. For error-free data communication, the parameters for baud rate, parity, handshake mode and character format must be the same for both units.

You can set these parameters in the Setup menu so that they match those of the connected device. You can also define parameters in the balance/scale to make data output dependent on various conditions. The conditions that can be configured are listed in the descriptions of the application programs.

If you do not connect a peripheral device to the interface port, this will not generate an error message.

#### Handshake

The balance/scale interface (Sartorius Balance Interface = SBI) has transmit and receive buffers. You can define the handshake parameter in the Setup menu:

- Hardware handshake (CTS/DTR)
- Software handshake (XON, XOFF)

#### Hardware Handshake

With a 4-wire interface, 1 more character can be transmitted after CTS (Clear to Send).

#### Software Handshake

The software handshake is controlled via XON and XOFF. When a device is switched on, XON must be transmitted to enable any connected device to communicate.

#### **Data Output by Print Command**

The print command can be transmitted by pressing (a) or by a software command (Esc P).

#### **Automatic Data Output**

Activate the "auto print" operating mode to have data output to the interface port without a print command. You can have data output automatically at defined display update intervals, with or without the stability parameter. The length of a print interval depends on the operating menu settings for AMBIENT (ambient conditions) (menu code 1. 1. 1. x) and AUT. EYEL. (time-dependent autom. printing; menu code 1. 6. 3. x).

If you activate the auto print setting, data will be transmitted immediately the moment you turn on the balance/scale. In the operating menu, you can define whether automatic printing can be stopped by pressing (3).

## **Pin Assignment Chart**

#### Female Interface Connector:

\*) = Hardware restart

25-contact D-Submini (DB25S) with screw lock hardware

Male connector used (please use connectors with the same specifications): 25-contact D-Submini (DB25S) with integrated shielded cable clamp assembly (Amp 826 985-1C) and fastening screws (Amp 164 868-1)

#### **△ Warning When Using Pre-wired RS-232 Connecting Cables:**

The pin assignments in RS-232 cables purchased from other manufacturers may be incompatible with Sartorius weighing instruments. Be sure to check the pin assignments against the chart below before connecting the cable, and disconnect any lines identified differently from those specified by Sartorius (e.g., pin 6).


Failure to do so may damage or even completely ruin your balance/scale and/or peripheral device(s).

#### Pin assignments: Pin 1: Signal ground 100000000000013) Pin 2: Data output (TxD) 140000000000000025 Pin 3: Data input (RxD) Pin 4: Internal ground (GND) Pin 5: Clear to send (CTS) Pin 6: Not connected Pin 7: Internal ground (GND) Pin 8: Internal ground (GND) Pin 9: Not connected Pin 10: Not connected Pin 11: +12 V (Power supply for Sartorius printer) Pin 12: Reset Out \*) For remote switch Pin 13: +5 V Pin 14: Internal ground (GND) Pin 15: Universal remote switch Pin 16: Not connected Pin 17: Not connected Pin 18: Not connected Pin 19: Not connected Pin 20: Data terminal ready (DTR) Pin 21: Not connected Pin 22: Not connected Pin 23: Not connected Pin 24: Not connected Pin 25: +5 V

## **Cabling Diagram**

For connecting a computer or other peripheral device to the balance/scale using the RS-232C/V24 protocol and cable lengths of up to 15 m (approx. 50 ft).

Important: do not connect any other pins to the cable connector of the balance/scale.



Cable type: AWG 24 specification

## **Troubleshooting Guide**

Error codes are shown on the main display for approx. 2 seconds. The program then returns automatically to the previous mode.

Display	Cause	Solution
No segments appear on the display	No AC power is available	Check the AC power supply
, ,	The power supply is not plugged in	Plug in the power supply
нІбн	The load exceeds the balance/ scale capacity	Unload the balance/scale
LOW or ERR 54	Something is touching the weighing pan	Move the object that is touching the weighing pan
APP.ERR.	Cannot store data: Load on weighing pan too light or no sample on pan while application is active	Increase load
DIS.ERR.	Data output not compatible with output format	Change the configuration in the operating menu
PRT.ERR.	Interface port for printer output is blocked	Reset the menu factory settings, or Contact your local Sartorius Service Center
ERR 02	Calibration parameter not met; e.g.: – balance/scale not tared – load on weighing pan	Calibrate only when zero is displayed  - Press (lare) to tare the balance/scale  - Unload the balance/scale
ERR IO	The lare key is blocked when there is data in the second tare memory (net-total); only 1 tare function can be used at a time	Press ©F to clear the tare memory and release the tare key
ERR II	Tare memory not allowed	Press Tare
The weight readout changes constantly	Unstable ambient conditions (excessive vibration or draft) at the place of installation	Set up the balance/scale in another area
	A foreign object is caught between weighing pan and balance/scale housing	Remove the foreign object
The weight readout is obviously wrong	The balance/scale was not calibrated/adjusted Balance/scale not tared	Calibrate/adjust the balance/scale  Tare or zero the balance/scale
	before weighing	before weighing

If any other errors occur, contact your local Sartorius Service Center.
Contact information: Please point your Internet browser to: http://www.sartorius.com

### **Care and Maintenance**

#### Service

On request, Sartorius can offer you an individual service contract.

#### Repairs

Repair work must be performed by trained service technicians. Any attempt by untrained persons to perform repairs may result in considerable hazards for the user.

#### Cleaning


- Unplug the AC adapter from the wall outlet (mains supply). If you have an interface cable connected to the balance/scale port, unplug it from the port.
- The plastic upper and lower segments of the balance/scale housing are protected by a special coating, so that they will not be damaged by the solvents usually used for cleaning.
- ⚠ Do not used solvents or aggressive cleaning agents on the following parts: keypad overlay, power jack, data interface
- After cleaning, wipe down the balance/scale with a soft, dry cloth.

On analytical balances remove and clean the weighing pan as follows:

- Reach beneath the shield disk and lift it carefully, together with the pan support, to avoid damaging the weighing system.
- Make sure that no liquid enters the balance/scale housing.

#### **Cleaning Stainless Steel Surfaces**

Clean all stainless steel parts regularly. Remove the stainless steel weighing pan and thoroughly clean it separately. Use a damp cloth or sponge to clean stainless steel parts on the balance/scale. You can use any household cleaning agent that is suitable for use on stainless steel. Clean stainless steel surfaces only by wiping them down. Then rinse the equipment thoroughly, making sure to remove all residues. Afterwards, allow the equipment to dry. If desired, you can apply oil to the cleaned surfaces as additional protection.



## Recycling

#### Safety Inspection

If there is any indication that safe operation of the balance/scale is no longer warranted:

- Turn off the power and disconnect the equipment from AC power immediately.
- > Lock the equipment in a secure place to ensure that it cannot be used for the time being.

Notify your nearest Sartorius Service Center. Repair work must be performed by trained service technicians.

We recommend having the power supply inspected by a certified electrician at regular intervals, according to the following checklist:

- Insulating resistance: > 7 megaohms measured with a constant voltage of at least 500 volts at a 500 K-ohm load
- Leakage current: < 0.05 mA measured with a properly calibrated multimeter

If you no longer need the packaging after successful installation of the equipment, you should return it for recycling. The packaging is made from environmentally friendly materials and is a valuable source of secondary raw material. Batteries are hazardous waste and must be disposed of seperately. Please deposit empty batteries in the collection boxes set up in your area for this purpose. On request, Sartorius can provide GRS boxes for collecting used batteries. (GRS stands for "Gemeinsames Rücknahme System," a German organization for battery disposal.\*)



Contact your local waste disposal authorities if you wish to scrap the equipment. Sartorius AG in Goettingen will take back equipment

and packaging for disposal in accordance with the applicable laws.\* If you set up the equipment in a country other than Germany, please contact your local waste disposal authorities for information on similar services.

\* This service is offered only within Germany

## **Overview**

### **Specifications**

#### **Specifications**

Built-in motorized calibration weight		All models with the designation suffix EDCW, GK, GW or with a readability of 0.0001 g and all verified models
AC power source/power requirements, voltage, frequency		AC adapter 230 V or 115 25 V, +15% to - 20%, 48-60 Hz
Power consumption	VA	maximum 16; typical 8 (STNG6)
Approx. hours of operation with the YRB05Z rechargeable battery pack (backlighting on)	h	35

#### **Ambient Conditions**

The specifications given here are ensured under the following ambient conditions:

Operating temperature range	+10 to +30°C (273 to 303 K, 50 to 86°F)	
Allowable ambient		
operating temperature	+5 to +40°C (41 to 104°F)	

Proper functioning is ensured within an ambient operating temperature range of 5 to 40°C (41 to 104°F).

**Model-specific Specifications** 

Model		ED224S	ED124S	GK1203	GK703/ GK703-ST	GK303
Weighing capacity		220 g	120 g	1200 ct	700 ct	300 ct
Readability		0.0001 g	0.0001 g	0.001 ct	0.001 ct	0.001 ct
Tare range (subtractive)		220 g	120 g	1200 ct	700 ct	300 ct
Repeatability (std. deviation)	≤±	0.0001 g	0.0001 g	0.001 ct	0.001 ct	0.001 ct
Linearity	≤±	0.0002 g	0.0002 g	0.002 ct	0.002 ct	0.002 ct
Response time (average)	S	2.5	2.5	1.5	1.5	1.5
Sensitivity drift within +10 to +30°C	≤±/K	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>			
Adaptation to ambient conditions					filter levels; on filter leve	l selected)
External calibration weight (of at least accuracy class)	g	200 (E2)	100 (E2)	200 (E2)	100 (F2)	50 (F2)
Net weight, approx.:	kg	4.8	4.8	4.7	4.7	4.7
Weighing pan size	mm	90 Ø	90 Ø	90 Ø	90 Ø/35 Ø	90 Ø
Whg. chamber height	mm	230	230	160	160/38	160
Dimensions (WxDxH)	mm	230 × 303	3 × 330	230 × 303	X × 260 Model GK70 230 × 303 ×	

		· · · J	3	<u> </u>		
Readability		0.001 g	0.001 g	0.001 g	0.001 g	0.005 ct
Tare range (subtractive)		620 g	420 g	320 g	150 g	2200 ct
Repeatability (std. deviation)	≤±	0.001 g	0.001 g	0.001 g	0.001 g	0.005 ct
Linearity	≤±	0.002 g	0.002 g	0.002 g	0.002 g	0.01 ct
Response time (average)	S	1	1	11	1.3	1
Sensitivity drift within +10 to +30°C	≤±/K	2 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>	2 · 10-6	3.3 · 10 <sup>-6</sup>	2 · 10 <sup>-6</sup>
Adaptation to ambient conditions				zed filter levels pends on filter		)
External calibration weight (of at least accuracy class)	g	500 (E2)	200 (E2)	200 (F1)	100 (F1)	
Net weight, approx:	kg	3.2 3.6	3.2 3.6 4.4	3.2 3.6 4.4	2.6   3.0   1	4.4
Weighing pan size	mm	115 Ø	115 Ø	115 Ø	115 Ø	115 Ø
Dimensions (WxDxH)	mm	230 × 303 × 136	230 × 303 × 1 EDDS: 230			230 × 303 × 260
Model		ED6202S   GW6202   ED6202S-CW	ED4202S   ED4202S -CW	ED3202S   GW3202   ED3202S-CW	ED2202S   ED2202S -CW	ED822   ED822 -CW
	g	GW6202	ED4202S	GW3202	ED2202S	ED822
Weighing capacity	g	GW6202   ED6202S-CW	ED4202S -CW	GW3202   ED3202S-CW	ED2202S -CW	ED822 -CW
Weighing capacity Readability		GW6202   ED6202S-CW 6200	<b>ED4202S</b> - <b>CW</b> 4200	GW3202   ED3202S-CW 3200	ED2202S -CW 2200	ED822 -CW 820
Weighing capacity Readability Tare range (subtractive)	g g	GW6202   ED6202S-CW 6200 0.01	<b>ED4202S -CW</b> 4200 0.01	GW3202   ED3202S-CW 3200 0.01	ED2202S -CW 2200 0.01	ED822 -CW 820 0.01
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation)	g g	GW6202   ED6202S-CW 6200 0.01 6200	<b>ED4202S -CW</b> 4200 0.01 4200	GW3202   ED3202S-CW 3200 0.01 3200	ED2202S -CW 2200 0.01 2200	ED822 -CW 820 0.01 820
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation) Linearity	g g ≤±g	GW6202   ED6202S-CW 6200 0.01 6200 0.01	ED4202S -CW 4200 0.01 4200 0.01	GW3202   ED3202S-CW 3200 0.01 3200 0.01	ED2202S -CW 2200 0.01 2200 0.01	ED822 -CW 820 0.01 820 0.01
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation) Linearity Stabilization time (typical) Sensitivity drift within	g g ≤±g ≤±g s	GW6202   ED6202S-CW 6200 0.01 6200 0.01 0.02	ED4202S -CW 4200 0.01 4200 0.01 0.02	GW3202   ED3202S-CW 3200 0.01 3200 0.01 0.02	ED2202S -CW 2200 0.01 2200 0.01 0.02	ED822 -CW 820 0.01 820 0.01 0.02
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation) Linearity Stabilization time (typical) Sensitivity drift within +10 to +30°C Adaptation to ambient	g g ≤±g ≤±g s	GW6202   ED6202S-CW 6200 0.01 6200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> By selection of	ED4202S -CW 4200 0.01 4200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> f 1 of 4 optimiz	GW3202   ED3202S-CW 3200 0.01 3200 0.01 0.02 1.1	ED2202S -CW 2200 0.01 2200 0.01 0.02 1.1 2 · 10 <sup>-6</sup>	ED822 -CW 820 0.01 820 0.01 0.02 1.0 5 · 10 <sup>-6</sup>
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation) Linearity Stabilization time (typical) Sensitivity drift within +10 to +30°C Adaptation to ambient conditions External calibration weight	g g s±g ≤±g s ≤±/K	GW6202   ED6202S-CW 6200 0.01 6200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> By selection of	ED4202S -CW 4200 0.01 4200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> f 1 of 4 optimiz	GW3202   ED3202S-CW 3200 0.01 3200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> zed filter levels;	ED2202S -CW 2200 0.01 2200 0.01 0.02 1.1 2 · 10 <sup>-6</sup>	ED822 -CW 820 0.01 820 0.01 0.02 1.0 5 · 10 <sup>-6</sup>
Weighing capacity Readability Tare range (subtractive) Repeatability (std. deviation) Linearity Stabilization time (typical) Sensitivity drift within +10 to +30°C Adaptation to ambient conditions External calibration weight (of at least accuracy class) Net weight, approx:	g g s±g ≤±g s ≤±/K	GW6202   ED6202S-CW 6200 0.01 6200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> By selection of display update	ED4202S -CW 4200 0.01 4200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> f 1 of 4 optimiz :: 0.05-0.4 (dep	GW3202   ED3202S-CW 3200 0.01 3200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> zed filter levels; pends on filter	ED2202S -CW 2200 0.01 2200 0.01 0.02 1.1 2 · 10 <sup>-6</sup> evel selected	ED822 -CW 820 0.01 820 0.01 0.02 1.0 5 · 10 <sup>-6</sup>

 $180 \times 180$ 

 $180 \times 180$ 

 $180 \times 180$ 

 $180 \times 180$ 

 $230 \times 303 \times 91$ 

mm

mm

ED623S

620 g

ED623S-CW

ED423S

420 g

ED423S-DS

ED323S

320 g

ED323S-DS

ED423S-CW ED323S-CW

ED153

150 g

ED153-CW

ED153-DS

GK2202

2200 ct

Model

Weighing capacity

Weighing pan size

Dimensions (WxDxH)

150 Ø

230×303×87

Model		ED8201   ED8201-CW	GW7201	ED5201   ED5201-CW	ED2201   ED2201-CW
Weighing capacity	g	8200	7200	5200	2200
Readability	g	0.1	0.1	0.1	0.1
Tare range (subtractive)	g	8200	7200	5200	2200
Repeatability (std. deviation)	≤±g	0.1	0.1	0.1	0.1
Linearity	≤±g	0.1	0.1	0.1	0.1
Response time (average)	S	1	1	1	1
Sensitivity drift within +10 to +30°C	≤±/K	10 · 10-6			
Adaptation to ambient conditions		By selection of 1 display update: (		filter levels; Is on filter level sel	ected)
External calibration weight (of at least accuracy class)	g	5000 (F2)	5000 (F2)	5000 (F2)	2000 (F2)
Net weight, approx.:	kg	2.7   3.5	2.7	2.7   3.5	2.7   3.5
Weighing pan size	mm	180 × 180			
Dimensions (WxDxH)	mm	230 × 303 × 91	·	<u> </u>	

## Accessories

<b>External calibration weights:</b> For model	Accuracy class	Weight in grams C	rder no.:
ED423S/DS	E2		CW5228-00
ED4235/D3	E2 E2		CW5528-00
ED6233 ED4202S	E2 E2		CW6228-00
ED42025 ED6202S, GW6202	E2 E2		CW6528-00
ED62025, GW6202 ED153S/DS	E2 F1		CW5138-00
ED323S/DS	F1		CW5138-00 CW5238-00
ED3235/D3 ED3202S, ED2202S	F1		CW6238-00
ED32025, ED22025	F1 F2		CW5548-00
ED822 ED2201	F2		CW6248-00
ED8201, ED5201	F2 F2		CW6548-00
· · · · · · · · · · · · · · · · · · ·	· =		
or alternatively	± 25 mg	5000 <b>Y</b>	SS653-00
Product	Order No.	Product	
Data printer	YDP03-0CE	Density determination kit <sup>1</sup> )	
with date, time, statistics		- for ED224S, ED124S	YDK01LP
evaluation, transaction			
counter functions and LCD		Standard Operating Procedure	
		optimum use of your balance/sca	ıle
Remote display <sup>1</sup> ), reflective	YRD02Z	in quality-management systems	YSL01E
(for connection to data interface port)		Industrial AC adapter, model IN	Go
data interface port)		protection rating: 1P65 in accord	
External rechargeable battery	nook	with EN 60529	ance
YRB05Z	раск	- for 230 V	69 71899
With battery-level indicator (LE	n).	- for 120 V	69 71500
can be recharged using the AC	D),	- 101 120 V	09 / 1300
adapter (charge time for comple	atob.	Data cable	
discharged battery pack: 15 hou		<ul><li>for connecting a computer</li></ul>	
see "Specifications" for hours of		witha USB port	YCC01-USBM2
To recharge the battery pack:	орегация.	•	TCCUT-USBIVIZ
	halamaa/saala	- for computer connection,	7257212
Unplug the AC adapter from the		25-pin	7357312
and plug it into the battery pac	K	– for computer connection, 9-pi	1 /35/314
SartoConnect 1),		Adapter cable	6965619
data transfer software for direct		from D-Sub 25-pin male	
transmission of weight values		connector to D-Sub 9-contact	
to another program (e.g., MS Ex	(cel)	female connector; length: 0.25 n	1
- with RS-232C		remare connector, rengan 6125 h	•
connecting cable, length:			
1 m (~20 in)	YSC01L		
- with RS-232C	.50012		
connecting cable, length:			
5 m (~16 ft)	YSC01L5		
- with RS-232C	1300113		
connecting cable, length:			
15 m (~50 ft)	YSC01L15	1) Not for verified models	
טו טפיין זוו כו	IJCUILIJ	) NOT TOT VEHICLE HIDUCIS	

	Universal remote control switch for remote control of the following functions:  (a) or a function key (see "Configuration" for details):	Order No.
	Foot switch with T-connector Hand switch with T-connector	YFS01 YHS02
	<b>T-connector</b> Note: The T-connector is not intended for connecting multiple intelligent peripheral devices, such as PCs OR YDP03-OCE printers.	YTC01
	<b>lonizing blower</b> for eliminating static electricity 220 V 110 V	YIB01-0DR YIB01-0UR
	<b>Stat-Pen anti-static device</b> for eliminating electrostatic charges on samples and containers (100 V to 230 V, 50/60 Hz)	YSTP01
- -	Anti-vibration balance/scale table for precise, reliable weighing operations made of cast stone with shock absorbers	YWT01 YWT03
	Bracket for wall mounting	YWT04
- - - - -	Gem trays/Weighing bowls 300 ml, weight: 86 g, stainless steel 1000 ml, wt.: 240 g, stainless steel 500 ml 300 ml, wt.: 22 g, aluminum 110 ml, 90 mm Ø, aluminum 270 ml, wt.: 62 g, 137 mm Ø, stainless steel 62 mm Ø, stainless steel 85 ml, 70 mm Ø, aluminum 180 ml, 90 mm Ø, aluminum 174 mm Ø, stainless steel	6407 641211 641212 69641304 69GP0003 YWP03G 6910848 YWP06G YWP05G YWP04G



### Declaration of Conformity to Council Directives 89/336/EEC and 73/23/EEC (amended by Directive 93/68/EEC)

The electronic precision weighing instrument of the series ED/GK/GW/XX....-....

meets the applicable requirements of the test standards listed below, in conjunction with the associated power supplies, auxiliary peripheral devices and installation equipment listed in Annex A2 (see Annex A1 for a technical description and a list of the individual versions).

#### 1. Electromagnetic Compatibility

1.1 Source for 89/336/EEC: Official Journal of the European Communities, No. 2004/C98/05

EN 61326 Electrical equipment for measurement, control and laboratory use EMC requirements

Limitation of emissions: Residential areas, Class B

Defined immunity to interference: Industrial areas, continuous unmonitored operation

#### 2. Safety of Electrical Equipment

2.1 Source for 73/23/EEC: Official Journal of the European Communities, No. 2004/C103/02

EN 61010 Safety requirements for electrical equipment for measurement, control and laboratory use Part 1: General requirements EN 60950-1 Information technology equipment Safety

Sartorius AG 37070 Goettingen, Germany 2005

Part 1: General requirements

W. Obermann Senior Vice President, R&D Electronic Engineering Mechatronics Division

Dr. D. Klausgrete Head of International Certification Management Mechatronics Division Sartorius AG Weender Landstrasse 94–108 37075 Goettingen, Germany

Phone +49.551.308.0 Fax +49.551.308.3289 www.sartorius.com

Copyright by Sartorius AG, Goettingen, Germany. All rights reserved. No part of this publication may be reprinted or translated in any form or by any means without the prior written permission of Sartorius AG. The status of the information, specifications and illustrations in this manual is indicated by the date given below. Sartorius AG reserves the right to make changes to the technology, features, specifications and design of the equipment without notice.

Status: October 2005, Sartorius AG, Goettingen, Germany

Printed in Germany on paper that has been bleached without any use of chlorine W1A000 · KT
Publication No.: WED6001-e05103